

Leghe comunemente utilizzate per la barra destinata allo stampaggio

CuZn36Pb2As CW602N	CuZn38Pb2 CW608N	CuZn39Pb1 CW611N	CuZn39Pb2 CW612N	CuZn39Pb2Sn CW613N
CuZn40Pb1Al CW616N	CuZn40Pb2 CW617N	CuZn35Pb1.5AlAs CW625N	CuZn33Pb1.5AlAs CW626N	ASTM C67300 Manganese Bronze
CuZn40 CW509L / C27450	CuZn42 CW510L / C28500	CuZn38As CW511L / C27453	CuZn37Mn3Al2PbSi CW713R	CuZn39Sn1 CW719R

Leghe comunemente utilizzate per la barra destinata alla torneria (barra piena)

CuZn36Pb2As CW602N	CuZn36Pb3 CW603N	CuZn37Pb1 CW605N	CuZn37Pb2 CW606N	CuZn38Pb 1 CW607N
CuZn38Pb2 CW608N	<i>SPM - Lega CG13</i>	CuZn39Pb2 CW612N	CuZn39Pb3 CW614N	CuZn40Pb2 CW617N
CuZn35Pb1.5AlAs CW625N	CuZn33Pb1.5AlAs CW626N	CuZn40 CW509L / C27450	CuZn42 CW510L / C28500	CuZn38As CW511L / C27453
CuZn37Mn3Al2PbSi CW713R				

Leghe comunemente utilizzate per la barra destinata alla torneria (barra forata)

CuZn36Pb2As CW602N	CuZn36Pb3 CW603N	CuZn37Pb1 CW605N	CuZn37Pb2 CW606N	CuZn38Pb2 CW608N
CuZn39Pb2 CW612N	CuZn39Pb3 CW614N	CuZn40Pb2 CW617N	CuZn35Pb1.5AlAs CW625N	CuZn33Pb1.5AlAs CW626N
CuZn40 CW509L / C27450	CuZn42 CW510L / C28500	CuZn38As CW511L / C27453	CuZn37Mn3Al2PbSi CW713R	

Leghe comunemente utilizzate per il filo

CuZn36 CW507L	CuZn37 CW508L	CuZn40 CW509L / C27450	CuZn40Si CF724R	
CuZn36Pb3 CW603N	CuZn37Pb2 CW606N	CuZn38Pb2 CW608N	CuZn39Pb2 CW612N	CuZn39Pb3 CW614N

Leghe comunemente utilizzate per il nastro

CuZn39Pb1 CW611N	CuZn39Pb2 CW612N			
---------------------	---------------------	--	--	--